

NEREZ**Nástrčné spojky**

z nerezové oceli



T-spojky s bočním kuželovým závitem				
Obj. č.	Hadička	Závit	Pracovní tlak (bar)	Pracovní teplota (°C)
RIX03-184	4 mm	R 1/8"	0 - 18	-15 / +110
RIX03-186	6 mm	R 1/8"	0 - 18	-15 / +110
RIX03-146	6 mm	R 1/4"	0 - 18	-15 / +110
RIX03-188	8 mm	R 1/8"	0 - 18	-15 / +110
RIX03-148	8 mm	R 1/4"	0 - 18	-15 / +110
RIX03-1410	10 mm	R 1/4"	0 - 18	-15 / +110
RIX03-3810	10 mm	R 3/8"	0 - 18	-15 / +110



Přímé spojky				
Obj. č.	Hadička 1	Hadička 2	Pracovní tlak (bar)	Pracovní teplota (°C)
RIX06-4	4 mm	4 mm	0 - 18	-15 / +110
RIX06-6	6 mm	6 mm	0 - 18	-15 / +110
RIX06-8	8 mm	8 mm	0 - 18	-15 / +110
RIX06-10	10 mm	10 mm	0 - 18	-15 / +110
RIX06-12	12 mm	12 mm	0 - 18	-15 / +110



Průchodky				
Obj. č.	Hadička	Závit na těle	Pracovní tlak (bar)	Pracovní teplota (°C)
RIX16-4	4 mm	M12×1	0 - 18	-15 / +110
RIX16-6	6 mm	M14×1	0 - 18	-15 / +110
RIX16-8	8 mm	M16×1	0 - 18	-15 / +110
RIX16-10	10 mm	M20×1	0 - 18	-15 / +110
RIX16-12	12 mm	M22×1	0 - 18	-15 / +110



L-spojky				
Obj. č.	Hadička	Pracovní tlak (bar)	Pracovní teplota (°C)	
RIX02-4	4 mm	0 - 18	-15 / +110	
RIX02-6	6 mm	0 - 18	-15 / +110	
RIX02-8	8 mm	0 - 18	-15 / +110	
RIX02-10	10 mm	0 - 18	-15 / +110	
RIX02-12	12 mm	0 - 18	-15 / +110	



T-spojky				
Obj. č.	Hadička 1	Hadička 2	Pracovní tlak (bar)	Pracovní teplota (°C)
RIX04-4	4 mm	4 mm	0 - 18	-15 / +110
RIX04-6	6 mm	6 mm	0 - 18	-15 / +110
RIX04-8	8 mm	8 mm	0 - 18	-15 / +110
RIX04-10	10 mm	10 mm	0 - 18	-15 / +110
RIX04-12	12 mm	12 mm	0 - 18	-15 / +110

související zboží:

Teflonové hadičky
str. 466Nerezové jednotky
str. 791Nerezové válce
str. 813Ventily
str. 869